

**OFFICE OF THE EXECUTIVE ENGINEER, SUB TRANS. DIVISION-II  
JAMMU.**

To

*M/S Electric field Co.,  
New Secretariate Road,  
Jammu.*

NO: STD/II/ 803 -05

Dated: 1-6-07

**Subject**      *Performance report of 11 KV,33 KV CT's.*

**Reference:**    *Your letter No: 492-05/EC/2007 dated: 2.5.2007*


**Dear Sir,**

Kindly refer to your above letter vide which the performance report of the following equipments supplied by your firm has been requested from this office.

1.      *1 set consisting 3 Nos. 33 KV Oil cooled, outdoor type Current Transformer having Primary ratio 75-150-300/5-5-5A installed at R/Stn. Sidhra.*
2.      *1 set consisting 3 nos. 11 KV oil cooled outdoor type current Transformer having Primary ratio 450A/2.89 A installed at R/Stn. Sidhra.*
3.      *1 set consisting 3 nos. 11 KV outdoor type oil cooled current transformer having Primary ratio 600-375/5/2.89 installed at R/Stn. Biaspur.*
4.      *1 set consisting 3 Nos. 33 KV outdoor type oil cooled current transformer having Primary ratio 125-200/5/5A installed at R/Stn. Biaspur.*
5.      *1 No. 11 KV Neutral Transformer having Primary ratio 600-375/5A installed at R/Stn. Biaspur.*

*It is intimated that the performance of the above equipment is satisfactory till date.*

*Yours Faithfully,*

  
*Executive Engineer,  
Sub Trans. Division-II,  
Jammu.*

**Copy to the:**

1.      *AEE, Sub Divn. I/III (STD-II) Jammu. This is as per report furnished by them.*